Colortrac SC/SCi Series
Update Firmware

Instruction Manual

Issue 1   Date: 20/05/2022

©Colortrac Ltd 2021

SC Scanners

SC25 Xpress 'm', 'c' & 'e'
SC36 Xpress 'm', 'c' & 'e'
SC42 Xpress 'm', 'c' & 'e'
**SC25 mfp, SC36 mfp & SC42 mfp**

SCi Scanners

SCi25 'm', 'c' & 'e'
**SCi36 'm', 'c' & 'e'**
SCi42 'm', 'c' & 'e'

1   Updating Firmware

1. Double click the SmartLF
    SC Utilities icon.

    SmartLF SC
    Utilities.exe

2. To enter the second level
    utilities Click 'Utilities' at the
    bottom of the front page.

3. Download the latest
    firmware from the download
    site:

    https://colortracsupport.com/scendusers.html

4. Click the browser button to
    locate the downloaded
    firmware. After selecting the
    firmware #########.cab
    file, click download.

5. Agree to the warning
    message.

*NOTE: It is important to allow the firmware
to complete. Although the* **Error! Reference
source not found.** *now carries a backup
firmware, there is still a possibility of
irreversible corrupting if the download is
disturbed.*

6. Once the download has
    finished it will request the
    scanner and software are
    both Re-cycled.